

Inspection Photos

November 1st, 2024

Operator: Morningstar Operating - 10755

Location ID: 334051

Inspection Document #: 714001429

Archuleta County, CO

Township: SESE 1 32N 6W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Swanemyr 32-6 1-2, 3
Location ID: 334051

11/1/24
269° W



Photo 1. View of well disturbance taken from the access point facing center.



Inspection Photos
Location Name: Swanemyr 32-6 1-2, 3
Location ID: 334051

11/1/24
260° W



Photo 2. View of the northern interim reclamation area composed predominantly of intermediate wheatgrass.



Inspection Photos
Location Name: Swanemyr 32-6 1-2, 3
Location ID: 334051



Photo 3. View of weedy debris in the southern interim reclamation area.

Inspection Photos
Location Name: Swanemyr 32-6 1-2, 3
Location ID: 334051

11/1/24
356° N



Photo 4. View of irrigated field reference area.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 007-06212, 06240