

Energy & Carbon Management Commission



# Silverton 4 North Tank Battery Facility ID #481826 Issue Report

Created on November 6, 2024

Captured on November 5, 2024



Type	Count
Missing Placard/ Capacity Label	4
Stained Soil	1



No.	Type	Severity	Created	Status	Cost of Repair
4	 Stained Soil	—	November 6, 2024	Open	—
6	 Missing Placard/ Capacity Label	—	November 6, 2024	Open	—
7	 Missing Placard/ Capacity Label	—	November 6, 2024	Open	—
8	 Missing Placard/ Capacity Label	—	November 6, 2024	Open	—
9	 Missing Placard/ Capacity Label	—	November 6, 2024	Open	—

Total: \$0.00

9 - Missing Placard/ Capacity Label

Open

Nov 5, 2024 at 11:50am



Details

Summary:

N/A

Created:

Nov 6, 2024, 10:57am by Adam Burns

Cost of Repair:

—

Lat/Long:

40.34123, -104.45018

8 - Missing Placard/ Capacity Label

Open

Nov 5, 2024 at 11:50am



Details

Summary:

N/A

Created:

Nov 6, 2024, 10:57am by Adam Burns

Cost of Repair:

—

Lat/Long:

40.34123, -104.45018

7 - Missing Placard/ Capacity Label

Open

Nov 5, 2024 at 11:50am



Details

Summary:

N/A

Created:

Nov 6, 2024, 10:56am by Adam Burns

Cost of Repair:

—

Lat/Long:

40.34131, -104.45012

6 - Missing Placard/ Capacity Label

Open

Nov 5, 2024 at 11:50am



Details

Summary:

N/A

Created:

Nov 6, 2024, 10:55am by Adam Burns

Cost of Repair:

—

Lat/Long:

40.34129, -104.45009

4 - Stained Soil

Open

Nov 5, 2024 at 11:50am



Details

Summary:

N/A

Created:

Nov 6, 2024, 10:54am by Adam Burns

Cost of Repair:

—

Lat/Long:

40.34090, -104.45096