

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RWF 324-9 Pad

Location ID: 311663



Photo # 9491 From entrance to location



Photo # 9492 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RWF 324-9 Pad

Location ID: 311663



Photo # 9493 Location



Photo # 9494 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RWF 324-9 Pad

Location ID: 311663




Photo # 9495 Location



Photo # 9496 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RWF 324-9 Pad

Location ID: 311663



Photo # 9497 Location



Photo # 9498 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RWF 324-9 Pad

Location ID: 311663



Photo # 9499 Location



Photo # 9500 Open ended piping/wildlife hazard

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RWF 324-9 Pad

Location ID: 311663



Photo # 9501 Open ended piping/wildlife hazard



Photo # 9502 Unused equipment on location