

Inspection Photos

November 1st, 2024

Operator: Petrox Resources INC - 69805

Location ID: 320886

Inspection Document #: 714001443

Archuleta County, CO

Township: NWNE 9 34N 5W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Fosset Gulch Unit 9U 2
Location ID: 320886



Photo 1. View of well disturbance taken from the access point facing center. Note: Local emergency contact # has been posted to the location sign.

Inspection Photos
Location Name: Fosset Gulch Unit 9U 2
Location ID: 320886



Inspection Photos

Location Name: Fosset Gulch Unit 9U 2

Location ID: 320886



Photo 3. Canada Thistle and Mullein observed in the southern portion of the location.

Inspection Photos
Location Name: Fosset Gulch Unit 9U 2
Location ID: 320886



Photo 4. View of reference area composed of Squirrel tail, Gambel Oak and Pine.

