

## Inspection Photos


Location: LARAMIE ENERGY LLC CC/604-41-32 Pad

Location ID: 335902

Date: 11/06/2024



Nov 6, 2024 at 1:15:08 PM  
+39.557232,-108.218019 ±4.73m  
De Beque



Nov 6, 2024 at 1:38:20 PM  
+39.557046,-108.218269 ±4.74m  
De Beque

Photo # 8756 Entrance to location

Photo # 8771 Location

## Inspection Photos

Location: LARAMIE ENERGY LLC CC/604-41-32 Pad

Location ID: 335902

Date: 11/06/2024



Photo # 8757 Location



Photo # 8761 Location



## Inspection Photos

Location: LARAMIE ENERGY LLC CC/604-41-32 Pad

Location ID: 335902

Date: 11/06/2024



Photo # 8762 Location



Photo # 8766 Location



## Inspection Photos

Location: LARAMIE ENERGY LLC CC/604-41-32 Pad

Location ID: 335902

Date: 11/06/2024



Photo # 8770 Location



Photo # 8788 SW corner of location



## Inspection Photos

Location: LARAMIE ENERGY LLC CC/604-41-32 Pad

Location ID: 335902

Date: 11/06/2024



Photo # 8789 NW corner of location



Photo # 8758 Improperly stored chemicals



## Inspection Photos

Location: LARAMIE ENERGY LLC CC/604-41-32 Pad

Location ID: 335902

Date: 11/06/2024



**Photo # 8765 Open ended piping/wildlife hazard/ available for entry by wildlife**



**Photo # 8768 Wildlife protection for containment needs maintenance/screen is damaged**