

Inspection Photos

Location Name: CAERUS PICEANCE LLC, WALLING-68S96W/1NWSE

Location ID: 334062

Date: 11/7/2024



Location Entrance – Photo #04764



Location – Photo #04771

Inspection Photos

Location Name: CAERUS PICEANCE LLC, WALLING-68S96W/1NWSE

Location ID: 334062

Date: 11/7/2024



Location – Photo #04766



Location – Photo #04765



Inspection Photos

Location Name: CAERUS PICEANCE LLC, WALLING-68S96W/1NWSE

Location ID: 334062

Date: 11/7/2024



Location – Photo #04770



Wildlife Entry Hazard – Photo #04767

Inspection Photos

Location Name: CAERUS PICEANCE LLC, WALLING-68S96W/1NWSE

Location ID: 334062

Date: 11/7/2024



Wildlife Entry Hazard – Photo #04768



Wildlife Entry Hazard – Photo #04769



Inspection Photos

Location Name: CAERUS PICEANCE LLC, WALLING-68S96W/1NWSE

Location ID: 334062

Date: 11/7/2024



Lack of Stabilization – Photo #04772



Insufficient Tracking BMPs – Photo #04773