

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PA-67S95W/6NENW

Location ID: 334628

Date: 11/8/2024



Location – Photo #04801




Location – Photo #04808

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PA-67S95W/6NENW

Location ID: 334628

Date: 11/8/2024



Tank Battery – Photo #04805



Open Wellhead Cellar/No Wildlife Egress – Photo #04802

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PA-67S95W/6NENW

Location ID: 334628

Date: 11/8/2024



Open Wellhead Cellar/No Wildlife Egress – Photo #04803



Open Wellhead Cellar/No Wildlife Egress – Photo #04804