

# Inspection Photos

November 12th, 2024

Operator: Simcoe LLC - 10749

Location ID: 326601

Inspection Document #: 714001475

La Plata County, CO

Township: NWNE 6 34N 7W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Gearhart B 2  
Location ID: 326601



11/12/24  
20° N



11/12/24  
312° NW


Photo 1. View of well disturbance taken from the access point facing center.

Inspection Photos  
Location Name: Gearhart B 2  
Location ID: 326601



**Photo 2.** Eastern interim reclamation area composed of Rabbitbrush, Western Wheatgrass and Little Bluestem. No weeds observed on location.

Inspection Photos  
Location Name: Gearhart B 2  
Location ID: 326601



**Photo 3.** Impacted surface material observed at well head.

Inspection Photos  
Location Name: Gearhart B 2  
Location ID: 326601



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 4.** Reference area composed of predominantly Rabbitbrush and Western Wheatgrass.

API #: 067-08378