

Inspection Photos

Location Name: CAERUS PICEANCE LLC, CHEVRON-66S96W/4SWSW

Location ID: 335566

Date: 11/12/2024



Location – Photo #04847



Location – Photo #04850

Inspection Photos

Location Name: CAERUS PICEANCE LLC, CHEVRON-66S96W/4SWSW

Location ID: 335566

Date: 11/12/2024



Location – Photo #04854



Unmarked Deadman – Photo #04849

Inspection Photos

Location Name: CAERUS PICEANCE LLC, CHEVRON-66S96W/4SWSW

Location ID: 335566

Date: 11/12/2024



Lack of Stabilization – Photo #04848



Insufficient Tracking BMPs – Photo #04858