

Inspection Photos

Location Name: CAERUS PICEANCE LLC, CHEVRON/036B 596

Location ID: 335658

Date: 11/12/2024



Location Entrance/Lack of Stabilization – Photo #04871



Location – Photo #04872

Inspection Photos

Location Name: CAERUS PICEANCE LLC, CHEVRON/036B 596

Location ID: 335658

Date: 11/12/2024



Location – Photo #04874



Location – Photo #04875

Inspection Photos

Location Name: CAERUS PICEANCE LLC, CHEVRON/036B 596

Location ID: 335658

Date: 11/12/2024



Lack of Stabilization – Photo #04873



Insufficient Tracking BMPs – Photo #04876