

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/20NWSE

Location ID: 324126

Date: 11/14/2024



Location – Photo #04885



Location – Photo #04886

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/20NWSE

Location ID: 324126

Date: 11/14/2024



Location – Photo #04887



Location – Photo #04890

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/20NWSE


Location ID: 324126

Date: 11/14/2024



Nov 14, 2024 at 10:44:44
8311 CR-215
Parachute CO 81650
United States

Open-Ended Line – Photo #04888



Nov 14, 2024 at 10:44:50
8311 CR-215
Parachute CO 81650
United States

Open-Ended Line – Photo #04889

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/20NWSE

Location ID: 324126

Date: 11/14/2024



Open-Ended Vent on Tank – Photo #04891

