

Inspection Photos

November 12th, 2024

Operator: Simcoe LLC - 10749

Location ID: 325881

Inspection Document #: 714001490

La Plata County, CO

Township: NWSE 8 34N 7W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Bush Federal 1
Location ID: 325881



Photo 1. View of well disturbance taken from the access point facing center.

Inspection Photos
Location Name: Bush Federal 1
Location ID: 325881

11/12/24
80° E



Inspection Photos
Location Name: Bush Federal 1
Location ID: 325881



Photo 3. Stormwater erosion forming/rutting occurring on the southern edge of the active pad.

Inspection Photos
Location Name: Bush Federal 1
Location ID: 325881



Photo 4. Eastern interim reclamation composed of Indian Ricegrass, Rubber Rabbitbrush and Crested Wheatgrass.