

Inspection Photos

November 12th, 2024

Operator: Simcoe LLC - 10749

Location ID: 326668

Inspection Document #: 714001491

La Plata County, CO

Township: NENE 8 34N 7W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Bush Federal 2
Location ID: 326668



Photo 1. View of well disturbance taken from the access point facing center.

Inspection Photos
Location Name: Bush Federal 2
Location ID: 326668



Inspection Photos
Location Name: Bush Federal 2
Location ID: 326668



Photo 3. Placards at separator are deteriorating and illegible.

Inspection Photos
Location Name: Bush Federal 2
Location ID: 326668



Photo 4. Reference area composed of Gambel Oak, Pine and Smooth Brome.