

Inspection Photos

Location Name: CAERUS PICEANCE LLC, CHEVRON D20 696

Location ID: 335161

Date: 11/14/2024



Location Entrance – Photo #04922



Location – Photo #04926

Inspection Photos

Location Name: CAERUS PICEANCE LLC, CHEVRON D20 696

Location ID: 335161

Date: 11/14/2024



Location – Photo #04925



Location – Photo #04924

Inspection Photos

Location Name: CAERUS PICEANCE LLC, CHEVRON D20 696

Location ID: 335161

Date: 11/14/2024



Stored Supplies – Photo #04923



Lack of Stabilization – Photo #04930

Inspection Photos


Location Name: CAERUS PICEANCE LLC, CHEVRON D20 696

Location ID: 335161

Date: 11/14/2024



Lack of Stabilization – Photo #04929



Insufficient Tracking BMPs – Photo #04932