

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, BORUCH-67S96W/11NESE

Location ID: 334984

Date: 11/18/2024



Location Entrance – Photo #04936



Location – Photo #04934



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, BORUCH-67S96W/11NESE

Location ID: 334984

Date: 11/18/2024



Location – Photo #04939



Location – Photo #04938



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, BORUCH-67S96W/11NESE

Location ID: 334984

Date: 11/18/2024



Weathered and Illegible Wellhead Sign – Photo #04935



Open-Ended Line – Photo #04940

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, BORUCH-67S96W/11NESE

Location ID: 334984

Date: 11/18/2024



Open-Ended Line – Photo #04941



Open-Ended Line – Photo #04942