

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, C&C Energy GM/313-12 Frac Pad

Location ID: 334646

Date: 11/18/2024



Location Entrance – Photo #04962



Location – Photo #04969

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, C&C Energy GM/313-12 Frac Pad

Location ID: 334646

Date: 11/18/2024



Location – Photo #04968




Location – Photo #04967

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, C&C Energy GM/313-12 Frac Pad

Location ID: 334646

Date: 11/18/2024



Weathered and Illegible Wellhead Sign – Photo #04966



Open Wellhead Cellar/No Wildlife Egress – Photo #04965

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, C&C Energy GM/313-12 Frac Pad

Location ID: 334646

Date: 11/18/2024



Open Wellhead Cellar/Insufficient Wildlife Egress – Photo #04963



Open Wellhead Cellar/Insufficient Wildlife Egress – Photo #04964