

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, WATSON RANCH PAD/24B-17-07-95

Location ID: 413055

Date: 11/19/2024



Location Entrance – Photo #04971



Location – Photo #04972

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, WATSON RANCH PAD/24B-17-07-95

Location ID: 413055

Date: 11/19/2024



Nov 19, 2024 at 12:09:22
Parachute CO 81635
United States

Location – Photo #04975



Nov 19, 2024 at 12:08:32
Parachute CO 81635
United States

Location – Photo #04973

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, WATSON RANCH PAD/24B-17-07-95

Location ID: 413055

Date: 11/19/2024



Location – Photo #04979



Wildlife Entry Hazard – Photo #04977



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, WATSON RANCH PAD/24B-17-07-95

Location ID: 413055

Date: 11/19/2024



Wildlife Entry Hazard – Photo #04978



Open-Ended Lines on Separators – Photo #04976