

## Inspection Photos

Location: LARAMIE ENERGY LLC Castle Rock/18-4 Pad

Location ID: 312652

Date: 11/20/2024



Photo # 9262 Entrance to location




Photo # 9293 Location

## Inspection Photos

Location: LARAMIE ENERGY LLC Castle Rock/18-4 Pad

Location ID: 312652

Date: 11/20/2024



Photo # 9266 Location



Photo # 9270 Location



## Inspection Photos

Location: LARAMIE ENERGY LLC Castle Rock/18-4 Pad

Location ID: 312652

Date: 11/20/2024



Photo # 9291 Location



Photo # 9316 NW corner of location

## Inspection Photos

Location: LARAMIE ENERGY LLC Castle Rock/18-4 Pad

Location ID: 312652

Date: 11/20/2024



Photo # 9318 SW corner of location



Photo # 9319 SE corner of location



## Inspection Photos

Location: LARAMIE ENERGY LLC Castle Rock/18-4 Pad

Location ID: 312652

Date: 11/20/2024



Photo # 9321 NE corner of location



Photo # 9300 Tank failure/Tank lacks integrity

## Inspection Photos

Location: LARAMIE ENERGY LLC Castle Rock/18-4 Pad

Location ID: 312652

Date: 11/20/2024



Photo # 9303 Tank failure/Tank lacks integrity



Photo # 9275 Open hole on separator building/wildlife hazard available for entry by wildlife



## Inspection Photos

Location: LARAMIE ENERGY LLC Castle Rock/18-4 Pad

Location ID: 312652

Date: 11/20/2024



**Photo # 9278 Open hole on separator building/wildlife hazard available for entry by wildlife**



**Photo # 9279 Open holes on separator building/wildlife hazard available for entry by wildlife**

## Inspection Photos


Location: LARAMIE ENERGY LLC Castle Rock/18-4 Pad

Location ID: 312652

Date: 11/20/2024



**Photo # 9282 Gas meter building roof paneling damaged/wildlife hazard available for entry by wildlife**



**Photo # 9288 Gas meter building roof paneling damaged/wildlife hazard available for entry by wildlife**