

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
404003858

Date Received:
11/22/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 4 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

SIMCOE

sjninspections@ikavenergy.co

ECMC INSPECTION SUMMARY:

FIR Document Number: 714001415

Inspection Date: 10/28/2024

FIR Submit Date: 10/31/2024

FIR Status: _____

Inspected Operator Information:

Company Name: SIMCOE LLC

Company Number: 10749

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 333627

Location Name: COLORADO 32-7-N32N7W Number: 3SWNE County: LA PLATA

Qtrqtr: SWNE Sec: 3 Twp: 32N Range: 7W Meridian: N

Latitude: 37.049361 Longitude: -107.591988

FACILITY - API Number: 05-067-00 Facility ID: 216253

Facility Name: SCHOFIELD A Number: 1

Qtrqtr: SWNE Sec: 3 Twp: 32N Range: 7W Meridian: N

Latitude: 37.049361 Longitude: -107.591988

CORRECTIVE ACTIONS:

2 CA# 200194

Corrective Action: Maintain equipment and clean up impacted material and dispose per Rule 906 and 1002.

Date: 11/05/2024

Response: CA COMPLETED

Date of Completion: 11/20/2024

Operator Comment: Stained soil removed.

ECMC Decision: _____

ECMC Representative:	
----------------------	--

ECMC Representative:	
----------------------	--

Comment:	Corrective Actions completed. See attached photos.
----------	--

Title: Permitting Specialist I Date: 11/22/2024 10:15:46 AM

<u>Document Number</u>	<u>Description</u>
404003858	FIR RESOLUTION SUBMITTED
404003878	Schofield A1 CA photos

Page 2 of 2