

Inspection Photos

Location: LARAMIE ENERGY LLC Wagon Track Federal/12-14 Pad

Location ID: 312656

Date: 11/20/2024



Photo # 9436 Entrance to location




Photo # 9455 Location

Inspection Photos

Location: LARAMIE ENERGY LLC Wagon Track Federal/12-14 Pad

Location ID: 312656

Date: 11/20/2024



Photo # 9440 Location



Photo # 9446 Location

Inspection Photos

Location: LARAMIE ENERGY LLC Wagon Track Federal/12-14 Pad

Location ID: 312656

Date: 11/20/2024



Photo # 9454 Location



Photo # 9460 SW corner of location

Inspection Photos

Location: LARAMIE ENERGY LLC Wagon Track Federal/12-14 Pad

Location ID: 312656

Date: 11/20/2024



Photo # 9461 SE corner of location



Photo # 9462 NE corner of location

Inspection Photos

Location: LARAMIE ENERGY LLC Wagon Track Federal/12-14 Pad

Location ID: 312656

Date: 11/20/2024



Photo # 9463 NW corner of location



Photo # 9467 Gas meter building/siding is damaged/wildlife hazard available for entry by wildlife