

Inspection Photos

Location: LARAMIE ENERGY LLC Wagon Track Federal/12-16 Pad

Location ID: 312657

Date: 11/21/2024



Photo # 9544 Entrance to location



Photo # 9562 Location

Inspection Photos

Location: LARAMIE ENERGY LLC Wagon Track Federal/12-16 Pad

Location ID: 312657

Date: 11/21/2024



Photo # 9545 Location



Photo # 9550 Location

Inspection Photos

Location: LARAMIE ENERGY LLC Wagon Track Federal/12-16 Pad

Location ID: 312657

Date: 11/21/2024



Nov 21, 2024 at 12:45:34 PM
+39.282038,-108.272607 ±4.74m
De Beque



Nov 21, 2024 at 12:59:05 PM
+39.282194,-108.272748 ±4.73m
De Beque

Photo # 9559 Location

Photo # 9569 NW corner of location

Inspection Photos

Location: LARAMIE ENERGY LLC Wagon Track Federal/12-16 Pad

Location ID: 312657

Date: 11/21/2024



Nov 21, 2024 at 12:59:58 PM
+39.281864,-108.272686 ±4.73m
De Beque



Nov 21, 2024 at 1:02:33 PM
+39.282232,-108.272166 ±4.74m
De Beque

Photo # 9570 SW corner of location

Photo # 9571 NE corner of location

Inspection Photos

Location: LARAMIE ENERGY LLC Wagon Track Federal/12-16 Pad

Location ID: 312657

Date: 11/21/2024



Nov 21, 2024 at 1:05:14 PM
+39.281921,-108.272161 ±4.73m
De Beque



Nov 21, 2024 at 12:43:44 PM
+39.282121,-108.272387 ±4.74m
De Beque

Photo # 9572 SE corner of location

Photo # 9557 Gas meter building roof paneling is damaged/wildlife hazard available for entry by wildlife