

Caerus Piceance – QB Energy  
Figure Four Unit 8016B P09 498  
Location ID: 316333



**When replaced additional information will be required**

**Unused equipment**

Caerus Piceance – QB Energy  
Figure Four Unit 8016B P09 498  
Location ID: 316333



**When replaced additional information will be required**

**Unused equipment**

Caerus Piceance – QB Energy  
Figure Four Unit 8016B P09 498  
Location ID: 316333



Debris



Debris

Caerus Piceance – QB Energy  
Figure Four Unit 8016B P09 498  
Location ID: 316333



**Force required to access gas meter**



**Unused equipment**

Caerus Piceance – QB Energy  
Figure Four Unit 8016B P09 498  
Location ID: 316333



Debris



Location from South entrance

Caerus Piceance – QB Energy  
Figure Four Unit 8016B P09 498  
Location ID: 316333



Location from Northeast corner



Location from Northwest corner