

Final Reclamation and Stormwater Inspection

October 17, 2024

Operator: ANTELOPE ENERGY COMPANY LLC #3250

Location ID: 316746

Inspection Document #: 712300098

Routt County, CO

Logan Maxwell
Reclamation Specialist, ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos
Location Name: STATE-66N89W 15NWNE
Location ID: 316746



Photo 1. Photo taken from the Location entrance on the west end of the site, facing east. Photo provides an overview of the Location.



Photo 2. Photo taken the entrance of the Location, facing northeast. Photo illustrates that not all areas have achieved uniform vegetation across the Location.

Inspection Photos
Location Name: STATE-66N89W 15NWNE
Location ID: 316746



Photo 3. Photo taken from center of Location, facing southeast. Lighter vegetation (red arrow) seen in photo is Kochia, and Undesirable Plant Species not reflective of the reference area vegetation. Location is not progressing towards a uniform, desirable perennial vegetative cover, and additional reclamation efforts are required.



Photo 4. Photo taken from the eastern area of pad, facing south. Photo illustrates dense patches of undesirable plant species, circled in red (kochia).



Inspection Photos
Location Name: STATE-66N89W 15NWNE
Location ID: 316746



Photo 5. Photo taken from entrance of Location, facing access road towards the southwest. Perennial vegetation is failing to establish in the tracks. Compaction issues likely exist.



Inspection Photos
Location Name: STATE-66N89W 15NWNE
Location ID: 316746



Photo 8. Photo taken from the south of the Location, facing southwest. Photo illustrates reference area vegetation (Western wheatgrass, Basin wildrye).