

# Final Reclamation and Stormwater Inspection

October 17, 2024

Operator: TRUE OIL LLC #90450

Location ID: 418821

Inspection Document #: 712300099

Routt County, CO

Logan Maxwell  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Location Name: Breeze Unit 23-15

Location ID: 418821



**Photo 1.** Photo taken from the Location entrance on the west end of the site, facing southeast. Photo provides an overview of the Location.



**Photo 2.** Photo taken from the western portion of the Location, facing southeast. Photo illustrates that not all areas have achieved uniform vegetation; vegetation in disturbance (alfalfa, sweet clover) is not reflective of reference area vegetation (smooth brome).

Inspection Photos  
Location Name: Breeze Unit 23-15  
Location ID: 418821



**Photo 3.** Photo taken from center of Location, facing east, illustrating an overview of the location, and indicating differences in the disturbance area (red arrow) and reference area (blue arrow).



**Photo 4.** Photo taken from the northern area of pad, facing northwest, illustrating the difference between the disturbance and reference area vegetation. Areas to the left of the red line illustrate the disturbance area (sweet clover; alfalfa); areas to the right of the red line illustrate reference area vegetation (smooth brome).

Inspection Photos  
Location Name: Breeze Unit 23-15  
Location ID: 418821



**Photo 5.** Photo taken from northeastern edge of Location, facing reference area. Reference area appears to be mostly Smooth Brome.



Inspection Photos  
Location Name: Breeze Unit 23-15  
Location ID: 418821



**Photo 6.** Photo illustrates Undesirable weed species (Class B Noxious Weed - Bull Thistle). Comply with Rule 1004.e and Rule 606. Conduct weed management to prevent further establishment and spread of Undesirable Plant Species; ongoing weed management required until location passes final reclamation.



**Photo 7.** Photo illustrates Undesirable weed species (Class B Noxious Weed - Canada Thistle).



Inspection Photos  
Location Name: Breeze Unit 23-15  
Location ID: 418821



**Photo 8.** Photo taken of access road, facing southwest. It appears that the access road has not been reclaimed; compaction issues likely exist.



**Photo 9.** Photo taken of access road, facing northwest. Cheatgrass was observed along edges of road.