



Nov 21, 2024 1:30:08 PM

Inspection Photos
Location Name: Mccallum 121
Location ID: 057-06361
Inspection Date: 11/21/2024

Photo#1Well #121



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Mccallum 121
Location ID: 057-06361
Inspection Date: 11/21/2024

Photo #2 Wellhead. Based on salt staining on the fence, and around the wellhead, on the ground surface, and ice build up, it appears that fluids may have been leaking from the wellhead. No fluids were observed coming from the well at the time of inspection. ECMC called and left a message with the Operator at 0945 11/27/24. See comments in inspection.





Inspection Photos
Location Name: Mccallum 121
Location ID: 057-06361
Inspection Date: 11/21/2024

Photo#3 wellhead.

Nov 21, 2024 1:31:22 PM
40.75835160445422N 106.20964511297643W
Jc Road 19
Walden
Jackson County
Colorado



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Nov 21, 2024 1:31:34 PM
40.758364093489945N 106.20964301750064W
Jc Road 19
Walden
Jackson County
Colorado

Inspection Photos
Location Name: Mccallum 121
Location ID: 057-06361
Inspection Date: 11/21/2024

Photo#4 no belt guard.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources