

Inspection Photos
Location Name: Jillson 3
Location ID: 336406



Photo 1 Location.



Photo 2 Wellhead.

Inspection Photos
Location Name: Jillson 3
Location ID: 336406



Energy & Carbon Management Commission
40.1186, -104.99647, 4871.5ft, 97°
12/04/2024 13:43:59

Photo 3 Wellhead sign.



Energy & Carbon Management Commission
40.11864, -104.99663, 4881.3ft, 197°
12/04/2024 13:43:27

Photo 4 Ancillary equipment.

Inspection Photos
Location Name: Jillson 3
Location ID: 336406



Photo 5 Horse head lying on the ground.