

# Interim Reclamation and Stormwater Inspection

Date: 11/25/2024

Operator: HIGHPOINT OPERATING CORPORATION -  
10071

Location ID: 426426

Inspection Document #: 708201803

Weld County, CO



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: Bolin 6-62-13-24 NWNW  
Location ID: 423426



**Photo 1.** Google Earth aerial imagery (circa 09/2019) illustrating the access road (red outline) was constructed from WCR 85 to the drilling pad expansion (green outline) at Location ID (423426). At the time of this inspection, it does not appear that the access road has been reclaimed. See proceeding photos for additional information.



Inspection Photos  
Location Name: Bolin 6-62-13-24 NWNW  
Location ID: 423426



**Photos 2 & 3.** Taken from the easternmost point of the access road near WCR 85, facing southwest towards the location (left photo) and east towards WCR 85 (right photo). Photo illustrates road base material remains on the access road, which does not appear to have been reclaimed.



Inspection Photos  
Location Name: Bolin 6-62-13-24 NWNW  
Location ID: 423426



**Photo 4.** Taken from the approximate midpoint of the access road, facing east. Photo illustrates road base material remains on the access road, which does not appear to have been reclaimed.



Inspection Photos  
Location Name: Bolin 6-62-13-24 NWNW  
Location ID: 423426



**Photo 5.** Taken from the approximate midpoint of the access road, facing west. Photo illustrates road base material remains on the access road, which does not appear to have been reclaimed.



Inspection Photos  
Location Name: Bolin 6-62-13-24 NWNW  
Location ID: 423426



**Photo 6.** Taken from the access road north of the location, facing east. Photo illustrates road base material remains on the access road, which does not appear to have been reclaimed.



Inspection Photos  
Location Name: Bolin 6-62-13-24 NWNW  
Location ID: 423426



**Photo 7.** Google Earth aerial imagery (circa 09/2019) illustrating that location expansion for the drilling pad. AL wells 123-44395, 123-44400 and 123-44399 were not drilled based off of Form 4 Sundry notices indicating that the wells were not drilled and to abandon the permit. The location expansion/drilling pad appears to have been reclaimed at the time of this inspection, though the access road will need to be reclaimed

Inspection Photos  
Location Name: Bolin 6-62-13-24 NWNW  
Location ID: 423426



**Photo 8.** Facing north at the AL well locations. It appears that the operator has performed reclamation activities for the drilling pad. Additional reclamation activities are required for the access road north of the drilling pad/expansion.