

Inspection Photos

12/10/2024

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 383321

Inspection Doc: 718100113

Garfield County, CO

Aaron Trujillo
Western Reclamation Work Lead
ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 383321



December 10, 2024



December 10, 2024

Photo 1: Photos taken from the interim areas of the well pad. Limited inspection due to snow cover. Unable to find evidence within areas that were observable, that additional reclamation work has been performed, and BMPs to stabilize the seeded soils implemented. No resolution has been submitted stating work was performed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 383321



Photo 2: Photos taken from the interim areas of the battery facility. Limited inspection due to snow cover. Unable to find evidence within areas that were observable, that additional reclamation work has been performed, and BMPs to stabilize the seeded soils implemented. No resolution has been submitted stating work was performed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 383321



Photo 3: Photos taken from the interim areas of the battery facility. Limited inspection due to snow cover. Unable to find evidence within areas that were observable, that additional reclamation work has been performed, and BMPs to stabilize the seeded soils implemented. No resolution has been submitted stating work was performed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources