

# Inspection Photos

Loc: 483886

Operator: BNL (ENTERPRISE) INC

Inspection Date: 12/16/2024

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Drone aerial image facing west along the access road.





## Inspection Photos



**Photo 2.** Facing west toward the location.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:483886 | Date: 12/16/2024



## Inspection Photos



**Photo 3.** Facing southwest toward the location. The sign has fallen over and the silt fence is down and not maintained. Previous CA was not completed.





## Inspection Photos



**Photo 4.** Southeast corner of the location facing southwest. The silt fence is down and not maintained. The pile of debris in the corner has not been removed.





## Inspection Photos



**Photo 5.** Facing toward the soil stock pile. The topsoil has not been seeded and stabilized and the silt fence is in disrepair.





## Inspection Photos



**Photo 6.** Drone aerial image overlooking the location toward the northeast.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:483886 | Date: 12/16/2024



## Inspection Photos



**Photo 7.** Facing down toward the northwest corner showing the silt fence is not maintained and there is erosion riling along the cut slope.

