

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PORTER FEDERAL-66S92W/28SESW

Location ID: 335078

Date: 12/18/2024



Dec 18, 2024 at 13:17:35
Silt CO 81652
United States

Location – Photo #05392



Dec 18, 2024 at 13:18:02
Silt CO 81652
United States

Location – Photo #05393

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PORTER FEDERAL-66S92W/28SESW

Location ID: 335078

Date: 12/18/2024



Location – Photo #05394



Location – Photo #05398

Inspection Photos


Location Name: TEP ROCKY MOUNTAIN LLC, PORTER FEDERAL-66S92W/28SESW

Location ID: 335078

Date: 12/18/2024



Location – Photo #05413



Location – Photo #05395

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PORTER FEDERAL-66S92W/28SESW

Location ID: 335078

Date: 12/18/2024



Location – Photo #05396



Stored Equipment – Photo #05412

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PORTER FEDERAL-66S92W/28SESW

Location ID: 335078

Date: 12/18/2024



Damaged Tank Insulation – Photo #05405



Damaged Tank Insulation – Photo #05406

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PORTER FEDERAL-66S92W/28SESW

Location ID: 335078

Date: 12/18/2024



Damaged Tank Insulation – Photo #05407