

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, SPECIALTY-66S92W/21SWSE

Location ID: 335157

Date: 12/19/2024



Location Entrance – Photo #05469



Location – Photo #05471

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, SPECIALTY-66S92W/21SWSE

Location ID: 335157

Date: 12/19/2024



Location – Photo #05473



Location – Photo #05474



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, SPECIALTY-66S92W/21SWSE

Location ID: 335157

Date: 12/19/2024



**Weeds in Secondary Containment – Photo #05476**



**Weeds in Secondary Containment – Photo #05489**