

Inspection Photos
Location Name: Elkhorn Company B 5
Location ID: 318221



Photo 1 Wellsite.



Photo 2 Wellhead.

Inspection Photos
Location Name: Elkhorn Company B 5
Location ID: 318221



Photo 3 Wellhead sign.



Photo 4 Ancillary equipment.

Inspection Photos
Location Name: Elkhorn Company B 5
Location ID: 318221



Photo 5 Stained soil around the wellhead.



Photo 6 Leaking gasket staining pump jack concrete pad.

Inspection Photos
Location Name: Elkhorn Company B 5
Location ID: 318221



Photo 5 Stained concrete & soil on both sides of the pump jack.