

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, SPECIALTY-66S92W/28SENW

Location ID: 335147

Date: 12/19/2024



Location Entrance – Photo #05507



Location – Photo #05510

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, SPECIALTY-66S92W/28SENW

Location ID: 335147

Date: 12/19/2024



Location – Photo #05511



Location – Photo #05512

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, SPECIALTY-66S92W/28SEW

Location ID: 335147

Date: 12/19/2024



Stored Supplies – Photo #05526




Stored Supplies – Photo #05525

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, SPECIALTY-66S92W/28SEW

Location ID: 335147

Date: 12/19/2024



Dec 19, 2024 at 11:07:21  
Silt CO 81652  
United States



Dec 19, 2024 at 11:07:40  
Silt CO 81652  
United States

Stored Supplies – Photo #05519

Debris – Photo #05522

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, SPECIALTY-66S92W/28SEW

Location ID: 335147

Date: 12/19/2024



**Weeds – Photo #05509**



**Unprotected Soil Stockpile – Photo #05508**