

Operator: CPR

Location Name: GEIST-63N67W 32SWNW

Loc ID: 331237

Inspection: 716201337



CA: Weed debris at wellhead. Comply with Rule 606

CA Resolution: Operator has appropriately cleared weeds/debris from the wellhead to comply with 600 series.