

Inspection Photos

Location: QB ENERGY PUCKETT-67S97W/1NWSE (PUCKETT 255-1)

Location ID: 324204

Date: 01/7/2025



Photo # 2194 Entrance to location



Photo # 2204 Location

Inspection Photos

Location: QB ENERGY PUCKETT-67S97W/1NWSE (PUCKETT 255-1)

Location ID: 324204

Date: 01/7/2025



Photo # 2195 Location



Photo # 2198 Location

Inspection Photos

Location: QB ENERGY PUCKETT-67S97W/1NWSE (PUCKETT 255-1)

Location ID: 324204

Date: 01/7/2025




Photo # 2203 Location



Photo # 2222 NE corner of location

Inspection Photos

Location: QB ENERGY PUCKETT-67S97W/1NWSE (PUCKETT 255-1)

Location ID: 324204

Date: 01/7/2025



Jan 7, 2025 at 12:46:20 PM
+39.473341,-108.166254 ±4.13m
Parachute

Photo # 2224 SE corner of location



Jan 7, 2025 at 12:47:55 PM
+39.473254,-108.166996 ±3.73m
Parachute

Photo # 2225 SW corner of location

Inspection Photos

Location: QB ENERGY PUCKETT-67S97W/1NWSE (PUCKETT 255-1)

Location ID: 324204

Date: 01/7/2025



Photo # 2226 NW corner of location



Photo # 2206 Open ended load line/Trash

Inspection Photos

Location: QB ENERGY PUCKETT-67S97W/1NWSE (PUCKETT 255-1)

Location ID: 324204

Date: 01/7/2025




Photo # 2208 Wildlife hazard



Photo # 2210 Wildlife hazard

Inspection Photos

Location: QB ENERGY PUCKETT-67S97W/1NWSE (PUCKETT 255-1)

Location ID: 324204

Date: 01/7/2025



Photo # 2211 Wildlife hazard



Photo # 2214 Wildlife hazard

Inspection Photos

Location: QB ENERGY PUCKETT-67S97W/1NWSE (PUCKETT 255-1)

Location ID: 324204

Date: 01/7/2025



Photo # 2216 Wildlife hazard



Photo # 2219 Wildlife hazard

Inspection Photos

Location: QB ENERGY PUCKETT-67S97W/1NWSE (PUCKETT 255-1)

Location ID: 324204

Date: 01/7/2025



Photo # 2220 Wildlife hazard



Photo # 2221 Wildlife hazard