

Inspection Photos

Location: QB ENERGY PUCKETT-67S97W/1NWSE (PUCKETT 266-1)

Location ID: 324311

Date: 01/7/2025



Photo # 2231 Entrance to location



Photo # 2241 Location

Inspection Photos

Location: QB ENERGY PUCKETT-67S97W/1NWSE (PUCKETT 266-1)

Location ID: 324311

Date: 01/7/2025



Photo # 2232 Location




Photo # 2235 Location



Inspection Photos

Location: QB ENERGY PUCKETT-67S97W/1NWSE (PUCKETT 266-1)

Location ID: 324311

Date: 01/7/2025



Photo # 2239 Location



Photo # 2245 NE corner of location



Inspection Photos

Location: QB ENERGY PUCKETT-67S97W/1NWSE (PUCKETT 266-1)

Location ID: 324311

Date: 01/7/2025



Photo # 2246 SE corner of location



Photo # 2248 SW corner of location

Inspection Photos

Location: QB ENERGY PUCKETT-67S97W/1NWSE (PUCKETT 266-1)

Location ID: 324311

Date: 01/7/2025



Photo # 2249 NW corner of location

