

Inspection Photos
Location Name: Big Mountain Viper 8-59-16 PAD
Location ID: 472549



Photo 1 – Wellheads



Photo 2 – Wellhead Sign – 24 Hour Contact Number not current

Inspection Photos
Location Name: Big Mountain Viper 8-59-16 PAD
Location ID: 472549



Photo 3 – 24 Hour Contact Number not current

Photo 4 – 24 Hour Contact Number not current

Inspection Photos
Location Name: Big Mountain Viper 8-59-16 PAD
Location ID: 472549




Photo 5 – 24 Hour Contact number is not current



Photo 6 – Separators

Inspection Photos
Location Name: Big Mountain Viper 8-59-16 PAD
Location ID: 472549



Photo 7 – Gas Lift Injection Meter House



Photo 8 – Compressors

Inspection Photos
Location Name: Big Mountain Viper 8-59-16 PAD
Location ID: 472549



Photo 9 – Gas Sales Meter and Electrical and Automation Equipment



Photo 10 – VRU and Instrumental Air Unit

Inspection Photos
Location Name: Big Mountain Viper 8-59-16 PAD
Location ID: 472549



Photo 11 – ECDs



Photo 12 – LACT

Inspection Photos
Location Name: Big Mountain Viper 8-59-16 PAD
Location ID: 472549



Photo 13 – Tank Battery



Photo 14 – Sign at Entrance – 24 Hour Contact Number not current