

Inspection Photos
Location Name: Boomslang 8-60-14A PAD
Location ID: 454591



Photo 1 – Wellhead Sign – 24 Hour Contact Name and Number not current




Photo 2 – Wellhead Sign – 24 Hour Contact Name and Number not current

Inspection Photos
Location Name: Boomslang 8-60-14A PAD
Location ID: 454591




Photo 3 – Wellhead Sign – 24 Hour Contact Name and Number not current




Photo 4 – Wellhead Sign – 24 Hour Contact Name and Number not current

Inspection Photos
Location Name: Boomslang 8-60-14A PAD
Location ID: 454591



Photo 5 – Tank Label missing Content and Capacity Label



Photo 6 – 24-Hour Contact Name and Number are not current

Inspection Photos
Location Name: Boomslang 8-60-14A PAD
Location ID: 454591



Photo 7 – Tank Battery Sign




Photo 8 – Missing Content and Capacity Labels

Inspection Photos
Location Name: Boomslang 8-60-14A PAD
Location ID: 454591




Photo 9 – 24-Hour Contact Name and Number are not current




Photo 10 – Missing Content and Capacity Labels

Inspection Photos
Location Name: Boomslang 8-60-14A PAD
Location ID: 454591



Photo 11 – 24 Hour Contact Name and Number not current




Photo 12 – 24 Hour Contact Name and Number not current

Inspection Photos
Location Name: Boomslang 8-60-14A PAD
Location ID: 454591



Photo 13 – Sign at Entrance



Photo 14 – 24 Hour Contact Name and Number not current

Inspection Photos

Location Name: Boomslang 8-60-14A PAD

Location ID: 454591



Photo 15 – 24 Hour Contact Name and Number not current