

Inspection Photos

Location Name: Boomslang 8-60-14B PAD

Location ID: 455519




Photo 1 – Wellhead Sign – 24 Hour Contact Name and Number not current




Photo 2 – Tank Label – 24 Hour Contact Name and Number not current

Inspection Photos
Location Name: Boomslang 8-60-14B PAD
Location ID: 455519



Photo 3 – Capacity Label is fading; replace soon



Photo 4 – Wellhead Sign – 24 Hour Contact Name and Number not current

Inspection Photos
Location Name: Boomslang 8-60-14B PAD
Location ID: 455519



Photo 5 – 24-Hour Contact Name and Number are not current




Photo 6 – 24-Hour Contact Name and Number are not current

Inspection Photos
Location Name: Boomslang 8-60-14B PAD
Location ID: 455519



Photo 7 – 24-Hour Contact Name and Number are not current




Photo 8 – 24-Hour Contact Name and Number are not current

Inspection Photos
Location Name: Boomslang 8-60-14B PAD
Location ID: 455519




Photo 9 – 24-Hour Contact Name and Number are not current