

Inspection Photos

Location: QB ENERGY PUCKETT-67S97W/1SESW (PUCKETT 24B-1)


Location ID: 324395

Date: 01/7/2025



Jan 7, 2025 at 3:32:56 PM
+39.469990,-108.171526 ±6.59m
Parachute

Photo # 2328 Entrance to location



Jan 7, 2025 at 3:41:48 PM
+39.469735,-108.171170 ±7.23m
Parachute

WELL NAME	API#	LAT	LONG
Puckett 24B-1	05-045-13352	39.46958	-108.17094

ACCESSED BY- COUNTY ROAD 215
IN CASE OF EMERGENCY DIAL
970-285-2615 OR 911

Photo # 2346 Location



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

Location: QB ENERGY PUCKETT-67S97W/1SESW (PUCKETT 24B-1)

Location ID: 324395

Date: 01/7/2025



Jan 7, 2025 at 3:34:05 PM
+39.469599, -108.170997 ±3.97m
Parachute

Photo # 2329 Location



Jan 7, 2025 at 3:35:40 PM
+39.469599, -108.170997 ±3.97m
Parachute

Photo # 2333 Location

Inspection Photos

Location: QB ENERGY PUCKETT-67S97W/1SESW (PUCKETT 24B-1)

Location ID: 324395

Date: 01/7/2025



Photo # 2344 Location



Photo # 2350 SW corner of location

Inspection Photos

Location: QB ENERGY PUCKETT-67S97W/1SESW (PUCKETT 24B-1)

Location ID: 324395

Date: 01/7/2025



Photo # 2351 SE corner of location



Photo # 2352 NW corner of location

Inspection Photos

Location: QB ENERGY PUCKETT-67S97W/1SESW (PUCKETT 24B-1)

Location ID: 324395

Date: 01/7/2025



Photo # 2353 NE corner of location



Photo # 2339 Wildlife hazard

Inspection Photos

Location: QB ENERGY PUCKETT-67S97W/1SESW (PUCKETT 24B-1)

Location ID: 324395

Date: 01/7/2025



Photo # 2340 Wildlife hazard



Photo # 2342 Wildlife hazard