

# Inspection Photos

API: 071-06230

Operator: EVERGREEN NATURAL  
RESOURCES LLC

Inspection Date: 1/10/2025

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing northeast along the access road. There is erosion occurring along the roadside that will need to be repaired and stabilized.





## Inspection Photos



**Photo 2.** Facing back toward the erosion along the road side.





## Inspection Photos



**Photo 3.** Further along additional erosion is occurring.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

## Inspection Photos



**Photo 4.** Facing southwest at the wellsite.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



## Inspection Photos



**Photo 5.** Well sign posted at meter shed..



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API:071-06230 | Date: 1/10/2025