

Inspection Photos

API: 071-06237

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 1/10/2025

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northwest toward the wellsite.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 2. Facing toward the PW pit. Fence around the pit is maintained.



Inspection Photos



Photo 3. Facing toward the northwest side of the location. There is erosion occurring along this area which will need to be repaired and stabilized.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 4. Facing southwest at the drainage crossing at the west side of the location. The culvert has filled in with sediment and stormwater has begun to erode the road.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources