

Inspection Photos

API: 071-07259

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 1/10/2025

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing west along the access road. There is erosion along the road that needs to be repaired and stabilized..



Inspection Photos



Photo 2. Facing west further along the access road. There is erosion along the road that needs to be repaired and stabilized.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 3. Facing east at the culvert outlet along the road. The culvert outlet has eroded and needs to be repaired and outlet protection installed.



Inspection Photos



Photo 4. Facing southwest along the access road. There is erosion occurring across the road at this area.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 5. Facing southwest toward the wellsite.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 6. There are undesirable Russian thistle weeds at this location which may require control in the upcoming growing season.

