

Final Reclamation and Stormwater Inspection

Date: 01/10/2025

Operator: BONANZA CREEK ENERGY OPERATING
COMPANY LLC - 8960

Location ID: 305849

Inspection Document #: 708201930

Weld County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Pronghorn 14-8
Location ID: 305849



Photo 1. Facing northwest along the former access road. It appears that the former access road has been reclaimed with evidence of contouring and reseeding activities.

Inspection Photos
Location Name: Pronghorn 14-8
Location ID: 305849



Photo 2. Facing northwest near the former well location. It appears that the disturbance areas have been reclaimed with evidence of contouring and reseeding activities.

Inspection Photos
Location Name: Pronghorn 14-8
Location ID: 305849



Photo 3. Facing east near the former well location. See comments in Photo 2.

Inspection Photos
Location Name: Pronghorn 14-8
Location ID: 305849



Photo 4. Facing south near the former well location. See comments in Photo 2.

Inspection Photos
Location Name: Pronghorn 14-8
Location ID: 305849



Photo 5. Facing west near the former well location. See comments in Photo 2.