

**Inspection Photos**  
**Location Name: QB Energy MCU 26-12A (I27W) Pad**  
**Location #: 324383**



**Photo # 8080 From entrance to location**



**Photo # 8081 From entrance to location**

## Inspection Photos

Location Name: QB Energy MCU 26-12A (I27W) Pad

Location #: 324383




Photo # 8082 Location



Photo # 8083 Location



**Inspection Photos**  
**Location Name: QB Energy MCU 26-12A (I27W) Pad**  
**Location #: 324383**



**Photo # 8084 Location**




**Photo # 8085 Location**

**Inspection Photos**  
**Location Name: QB Energy MCU 26-12A (I27W) Pad**  
**Location #: 324383**



**Photo # 8086 Location**



**Photo # 8087 Location**






**Inspection Photos**  
**Location Name: QB Energy MCU 26-12A (I27W) Pad**  
**Location #: 324383**



**Photo # 8088 Location**



**Photo # 8089 Location**

**Inspection Photos**  
**Location Name: QB Energy MCU 26-12A (I27W) Pad**  
**Location #: 324383**



**Photo # 8090 Location**



**Photo # 8091 PRV vent line does not comply with CECMC pressure safety device rules**

**Inspection Photos**  
**Location Name: QB Energy MCU 26-12A (I27W) Pad**  
**Location #: 324383**



**Photo # 8092 PRV vent line does not comply with CECMC pressure safety device rules**



**Photo # 8093 PRV vent line does not comply with CECMC pressure safety device rules**