

Inspection Photos

01/08/2025

Operator: PUBLIC SERVICE COMPANY OF
COLORADO - 72400

Location ID: 312437

Inspection Doc: 718100176

Mesa County, CO

Aaron Trujillo
Western Reclamation Work Lead
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: PUBLIC SERVICE COMPANY OF COLORADO - 72400

Location ID: 312437



Photo 1: Photos 1-2 taken from the east end of the Location. Photos provide an overview of the Location from south, southwest, northwest to north.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: PUBLIC SERVICE COMPANY OF COLORADO - 72400

Location ID: 312437



Photo 2: See comments under photo 1. Photos also show tracking/rutting is becoming apparent. BMPs show sign of disrepair.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: PUBLIC SERVICE COMPANY OF COLORADO - 72400

Location ID: 312437



Photo 3: Photo shows hatch (arrow) at the produced water tank is open and currently venting to atmosphere.

Inspection Photos

Operator Name: PUBLIC SERVICE COMPANY OF COLORADO - 72400

Location ID: 312437



Photo 4: Photo example showing unmarked anchor (arrow) on the Location.

Inspection Photos

Operator Name: PUBLIC SERVICE COMPANY OF COLORADO - 72400

Location ID: 312437



Photo 5: Unused equipment, including buck that appears to contain oil fluids/rags stored behind equipment.