

Inspection Photos

January 13th, 2024

Operator: Simcoe LLC - 10749

Location ID: 325517

Inspection Document #: 714001697

La Plata County, CO

Township: SWNE 28 35N 8W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Davis 1-28 1
Location ID: 325517




Photo 1. View of well pad taken from the access point facing center.

Inspection Photos
Location Name: Davis 1-28 1
Location ID: 325517



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. View of separator labels that have deteriorated and are no longer legible.

API #: 067-06536



Inspection Photos
Location Name: Davis 1-28 1
Location ID: 325517



1/13/25
216° SW



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. Reference area composed of Pine, Gambel Oak, Smooth Brome and Broom Snakeweed.

API #: 067-06536