

Inspection Photos
Location Name: Musick-McClintock #3
Location ID: 311325



Photo 1: No sign displayed at tank battery




Photo 2: No sign displayed (contents, capacity)

Inspection Photos
Location Name: Musick-McClintock #3
Location ID: 311325



Photo 3: Overgrown vegetation




Photo 4: Overgrown vegetation

Inspection Photos
Location Name: Musick-McClintock #3
Location ID: 311325



Photo 5: Overgrown vegetation



Photo 6: Overgrown vegetation

Inspection Photos
Location Name: Musick-McClintock #3
Location ID: 311325



Photo 7: Overgrown vegetation



Photo 8: Wellhead Sign



Inspection Photos
Location Name: Musick-McClintock #3
Location ID: 311325



Photo 9: Pumpjack

