

Inspection Photos
Location Name: Musick-McClintock #1
Location ID: 332862



Photo 1: Tank Battery Sign (faded)

Photo 2: No capacity, contents displayed

Inspection Photos
Location Name: Musick-McClintock #1
Location ID: 332862



Photo 3: Overgrown vegetation

Photo 4: Overgrown vegetation

Inspection Photos
Location Name: Musick-McClintock #1
Location ID: 332862



Photo 5: Overgrown vegetation

Photo 6: Stained soil

Inspection Photos
Location Name: Musick-McClintock #1
Location ID: 332862



Photo 7: Dead, overgrown vegetation

Photo 8: Dead, overgrown vegetation

Inspection Photos
Location Name: Musick-McClintock #1
Location ID: 332862



Photo 9: Dead, overgrown vegetation

Photo 10: Dead, overgrown vegetation

Inspection Photos
Location Name: Musick-McClintock #1
Location ID: 332862



Photo 11: No sign displayed

Photo 12: Dead, overgrown vegetation