

**Inspection Photos**  
**Location Name: Musick-McClintock #7**  
**Location ID: 311363**



**Photo 1: Wellhead Sign, Operator name is not legible.**



**Photo 2: dead, overgrown vegetation. Unused equipment**

**Inspection Photos**  
**Location Name: Musick-McClintock #7**  
**Location ID: 311363**



**Photo 3: Dead, overgrown vegetation**



**Photo 4: Dead, overgrown vegetation**

**Inspection Photos**  
**Location Name: Musick-McClintock #7**  
**Location ID: 311363**



**Photo 5: Dead, overgrown vegetation**

